

# Inspection Photos

7/29/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335669

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335669



**Photo 1:** Photo taken from west end of the tank battery. Photo shows liner within secondary containment is in disrepair.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335669



**Photo 2:** Photo taken from the liner on the south end of the tank battery. Photo shows tear in liner.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335669



**Photo 3:** Photo taken from the north end of the Location, facing west. Photo shows slopes that remain loose material at risk to erosion; control measures to protect and stabilize slopes remain missing or insufficient.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335669



**Photo 4:** Photo taken from the north end of the Location, facing east. Photo shows slopes that remain loose material at risk to erosion; control measures to protect and stabilize slopes remain missing or insufficient.

