

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-16D Pad

Location ID: 335203



Network time is not synchronize  
Local: Jul 29, 2021 at 12:20:45 PM MD



Network time is not synchronize  
Local: Jul 29, 2021 at 12:20:47 PM MD

Photo #4603 from entrance to location.

Photo #4604 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-16D Pad

Location ID: 335203



**Photo #4605 No battery sign located at the tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-16D Pad

Location ID: 335203

