

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-15-23 Pad

Location ID: 335595



Photo #4609 from entrance to location.



Photo #4610 from entrance to location.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-15-23 Pad

Location ID: 335595



**Photo #4611 No battery sign located at the tank battery.**

**Photo #4612 unused equipment.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-15-23 Pad

Location ID: 335595



**Photo #4613 Multiple flow line heating insulation open ended and not capped.**



**Photo #4614 Location lacks stabilization.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0697-15-23 Pad

Location ID: 335595



**Photo #4615 Location lacks stabilization.**



**Photo #4616 No form of tracking BMP located at entrance to location.**