

## Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /23-15 Pad

Location ID: 324268



Photo #4622 from entrance to location.



Photo #4623 from entrance to location.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /23-15 Pad

Location ID: 324268



Network: Jul 29, 2021 at 2:22:51 PM MD

Local: Jul 29, 2021 at 2:22:46 PM MD

**Photo #4624 Multiple flow line heating insulation open ended and not capped.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources