

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S95W /3NENE

Location ID: 334647



Photo #4647 from entrance to location.




Photo #4648 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S95W /3NENE

Location ID: 334647



Photo #4649 from entrance to location.



Photo #4650 Location lacks stabilization.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S95W /3NENE

Location ID: 334647



Photo #4651 Location lacks stabilization.



Photo #4652 No form of tracking BMP at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources