

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/02/2021

Submitted Date:

08/02/2021

Document Number:

699104176

FIELD INSPECTION FORM

Loc ID 309980 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 295100 | WELL | TA | 05/18/2021 | GW | 123-25677 | AVA STATE C 36-22 | TA |

General Comment:

This is a follow up to FIRR #402764548. CA has been corrected.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | | |
|------|------|--------|--|--|--|
| | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 295100 Type: WELL API Number: 123-25677 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/05/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday 8/2/21 at approximately 0940hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR inspection document #402764548 at AVA State C 36-22 of Noble Energy, at Location ID #309980 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules.</p> <p>See attached photos.</p> <p>This is a summary of inspection report.</p> | burnsa | 08/02/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 699104177 | Inspection Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5496463 |