

Inspection Photos  
Operator: Simcoe  
API: 067-08707  
Date: 7/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing within the project area with western wheatgrass, James galleta, and crested wheatgrass. Dense musk thistles observed.





Photo 3. View of musk thistles within the project area in a flowering and seed dispersing condition. Approximately 150 individuals observed.





Photo 4. View of the reference area comprised of open pinyon and juniper woodland with understory of sagebrush, James galleta, penstemon, squirreltail and western wheatgrass.