

Final Reclamation Inspection

July 28, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 306265

Inspection Document #: 697503102

Weld County, CO

NWNW Section 5 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: REEMAN #11-5
Location ID: 306265



Photo 1. Google Earth aerial imagery taken 9/7/2016 during active operations. Photo illustrates the well location, well location access road and the offsite tank battery location.

Inspection Photos
Location Name: REEMAN #11-5
Location ID: 306265




Photo 2. Google Earth aerial imagery taken 10/14/2017 post plugging operations.

Inspection Photos
Location Name: REEMAN #11-5
Location ID: 306265



Photo 3. Drone aerial imagery taken from the wellhead, facing Northwest. Photo illustrates the associated tank battery is not reflective of reference area crops.

Inspection Photos
Location Name: REEMAN #11-5
Location ID: 306265



Photo 4. Photo taken from the eastern associated offsite tank battery, facing West. Photo illustrates the crop height is less than half of the reference areas throughout a majority of the location.

Inspection Photos
Location Name: REEMAN #11-5
Location ID: 306265



Photo 5. Drone aerial imagery taken from the wellhead, facing South. Photo illustrates the well location and the majority of the eastern reference field has stunted crop growth compared to the western field.