

Inspection Photos
Location Name: David Howard #2
Location ID: 317829



Photo1 Vegetation 4ft tall on access road.



Photo 2 Vegetation 4ft tall on access road.

Inspection Photos
Location Name: David Howard #2
Location ID: 317829



Photo 3 loc pic. Weeds on site around PU.



Photo 4 Well site sign faded not readable.