

Inspection Photos
Location Name: Farm Ranch Exploration 1
Location ID: 319972



Photo #1 Tanks.

Photo #2 Separator and ECD.

Inspection Photos
Location Name: Farm Ranch Exploration 1
Location ID: 319972



Photo #3 Pump jack.



Photo #4 weeds and dirt pile on east side of separator.

Inspection Photos
Location Name: Farm Ranch Exploration 1
Location ID: 319972



Photo #5 stained soil in west side of separator.



Photo # 6 weeds.