

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 1 WH sign

Photo 2 weeds overgrown around WH

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 3 Weeds growing around ancillary equipment

Photo 4 weeds overgrown around Pump Jack

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 5 Weeds over grown around location

Photo 6 weeds overgrown around Pump Jack

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 7 stained concrete pad under pump jack

Photo 8 trash on stained concrete pad leaking onto soil

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 9 stained soil by WH

Photo 10 stained concrete pad leaking onto soil

Inspection Photos
Location Name: Marie Gerhardt B5
Location ID: 318335



Photo 11 unused wiring where electric panel was