

# Inspection Photos

API: 071-07989

Operator: OGRIS OPERATING LLC

Inspection Date: 8/3/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07989 | Date: 8/3/2021

## Inspection Photos



**Photo 1.** There is erosion along the access road near the location. Areas of erosion need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07989 | Date: 8/3/2021



## Inspection Photos



**Photo 2.** The erosion continues off the side of the road from previous photo. this area needs to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07989 | Date: 8/3/2021



## Inspection Photos



**Photo 3.** Facing west toward the location. Noxious weed control has been performed at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07989 | Date: 8/3/2021