

Inspection Photos

API: 071-09111

Operator: OGRIS OPERATING LLC

Inspection Date: 8/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 1. Facing southeast along the main access road. The erosion along the road needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 2. The cattle guard is filled in with sediment and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 3. Facing back down the access road. There is erosion along the side of the road which needs BMP's to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 4. Facing back down the access road. There is erosion along the side of the road which needs BMP's to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021

Inspection Photos



Photo 6. There is a dripping water leak at the wellhead which is shown by the staining on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09111 | Date: 8/3/2021