

Inspection Photos

API: 071-09140

Operator: OGRIS OPERATING LLC

Inspection Date: 8/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09140 | Date: 8/3/2021

Inspection Photos



Photo 1. Facing northeast along the main access road. There is erosion along the side of the road which needs BMP's to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 8/3/2021

Inspection Photos



Photo 2. There is noxious weeds along the access road traveling to the location. Arrow points to Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 8/3/2021

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-09140 | Date: 8/3/2021

Inspection Photos



Photo 4. There is a dripping water leak at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 8/3/2021

Inspection Photos



Photo 5. There are some noxious weeds along the edge of the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 8/3/2021