

Inspection Photos

API: 071-07994

Operator: OGRIS OPERATING LLC

Inspection Date: 8/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07994 | Date: 8/3/2021

Inspection Photos



Photo 1. Facing northwest along the access road. The road has been graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07994 | Date: 8/3/2021

Inspection Photos



Photo 2. The culvert along the road has been repaired. There is some sediment beginning to accumulate which should be cleaned before it fills in.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07994 | Date: 8/3/2021

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07994 | Date: 8/3/2021

Inspection Photos



Photo 4. Facing northwest toward the access road that continues past the location. The road has been graded and culverts are maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07994 | Date: 8/3/2021