

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0603-23-32 Pad

Location ID: 335647



Photo #4663 from entrance to location.



Photo #4664 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0603-23-32 Pad

Location ID: 335647



Photo #4665 Location lacks stabilization.



Photo #4666 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0603-23-32 Pad

Location ID: 335647



Photo #4667 No form of tracking BMP at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources