

Final Reclamation Inspection

July 30, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 319365

Inspection Document #: 697503120

Weld County, CO

NWNE Section 18 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: TIGGES #31-18
Location ID: 319365




Photo 1. Google Earth aerial imagery taken 9/7/2016 taken during active operations. Photo illustrates the well location, well location access road and the offsite tank battery location. Note- the main access road appears to be pre-existing and appears to be used for agricultural activities.

Inspection Photos
Location Name: TIGGES #31-18
Location ID: 319365



Photo 2. Photo taken from the east access road, facing West. Photo illustrates the well location and access road are reflective of reference crop areas.



Inspection Photos
Location Name: TIGGES #31-18
Location ID: 319365



Photo 3. Photo taken from the associated offsite tank battery, facing West. Photo illustrates final reclamation has been performed; however, crop growth is stunted throughout the entire tank battery.



Inspection Photos
Location Name: TIGGES #31-18
Location ID: 319365



Photo 4. Photo taken east of the associated offsite tank battery, facing West. See comments under Photo 3.