

Final Reclamation Inspection

July 30, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 305335

Inspection Document #: 697503124

Weld County, CO

SWNE Section 18 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: TIGGES #18-13
Location ID: 305335




Photo 1. Google Earth aerial imagery taken 9/7/2016 taken during active operations. Photo illustrates the well location, well location access road and associated offsite tank battery. Note- the main access road appears to be pre-existing and appears to be used for agricultural activities.

Inspection Photos
Location Name: TIGGES #18-13
Location ID: 305335



Photo 2. Photo taken from the well location access, facing West. Photo illustrates the well location is reflective of reference crop areas.



Inspection Photos
Location Name: TIGGES #18-13
Location ID: 305335



Photo 3. Photo taken east of the associated offsite tank battery, facing West. Photo illustrates final reclamation has been performed; however, crop growth is stunted throughout the entire tank battery. This is being addressed under a separate inspection.

