

Final Reclamation Inspection

July 30, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 305336

Inspection Document #: 697503126

Weld County, CO

SENE Section 18 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TIGGES #18-14
Location ID: 305336



Photo 1. Google Earth aerial imagery taken 10/14/2017 taken during active operations. Photo illustrates the well location, well location access road and associated offsite tank battery. Note- the main access road appears to be pre-existing and appears to be used for agricultural activities.

Inspection Photos
Location Name: TIGGES #18-14
Location ID: 305336



Photo 2. Photo taken from the southern well location access road, facing North. Photo illustrates the well location and well location access road is reflective of reference crop areas.

Inspection Photos
Location Name: TIGGES #18-14
Location ID: 305336



Photo 3. Photo taken east of the associated offsite tank battery, facing West. Photo illustrates final reclamation has been performed; however, crop growth is stunted throughout the entire tank battery. This is being addressed under a separate inspection.

