

Inspection Photos

8/03/2021

Operator: SG INTERESTS I LTD #77330

Location ID: 324469

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD #77330
Location ID: 324469



Photo 1: Photo taken from the east end of the Location, facing west. Photo provides an overview of the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD #77330
Location ID: 324469



Photo 2: Photo taken from the north end of the Location (North of the tank battery). Photo shows noxious weeds (Canada thistle) established on the interim areas of the Location. Plants have matured and are currently seeding out.