

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NENW

Location ID: 334863



Photo #4682 from entrance to location.



Photo #4683 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NENW

Location ID: 334863



Photo #4684 Location lacks stabilization.



Photo #4685 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NENW

Location ID: 334863



Photo #4686 No form of tracking BMP at entrance to location.