

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWNW

Location ID: 334818



Photo #4687 from entrance to location.



Photo #4688 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWNW

Location ID: 334818



Photo #4689 No battery sign located at the tank battery.



Photo #4690 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWNW

Location ID: 334818



Photo #4691 Location lacks stabilization.



Photo #4692 No form of tracking BMP at entrance to location.