

TEP
A-29D
Location # 335629



location



location

TEP
A-29D
Location # 335629



location



Storage of supply/equipment



TEP
A-29D
Location # 335629



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
A-29D
Location # 335629



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
A-29D
Location # 335629



Cut slope not stabilized



Cut slope not stabilized



TEP
A-29D
Location # 335629



Cut slope not stabilized



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources