

Inspection Photos
Location Name: Green #1
Location ID: 319921



Photo 1 Weeds on access road



Photo 2 Mechanical issue and not E&P waste on ground.

Inspection Photos
Location Name: Green #1
Location ID: 319921



Photo 3 Weed and excess dirt on location.



Photo 4 Weeds around production equipment.

Inspection Photos
Location Name: Green #1
Location ID: 319921



Photo 5 Weeds inside tank battery containment.



Photo 6 TNK BTRY

Inspection Photos
Location Name: Green #1
Location ID: 319921



Photo 7 Gauge hatch open



Photo 8 loc pic

Inspection Photos
Location Name: Green #1
Location ID: 319921



Photo 9 No well head sign.