

Inspection Photos

API: 071-09542

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing southeast along the access road that remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 2. The access road is stabilized with gravel and vegetation. Culverts along the road are maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 3. Facing southeast along the access road toward the location. This area along the road side needs additional seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 4. This area along the road side needs additional seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 5. Facing southeast at the location. This culvert at the location has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 6. Facing southeast toward the location which remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 7. Facing southeast along the fill slope of the location. Perennial vegetation is well established along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 8. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021

Inspection Photos



Photo 9. This area needs additional seeding to help establish vegetation. There are areas of bed rock in this area but also areas of bare soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09542 | Date: 8/4/2021