

Inspection Photos

API: 071-09019

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09019 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09019 | Date: 8/4/2021

Inspection Photos



Photo 2. Facing southeast toward the well site. The location is stabilized with gravel and perennial vegetation is established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09019 | Date: 8/4/2021