

Inspection Photos

API: 071-09021

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing west toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/4/2021

Inspection Photos



Photo 2. Facing south toward the well site. The location is stabilized with gravel and perennial vegetation is established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/4/2021

Inspection Photos



Photo 3. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/4/2021