

Inspection Photos

API: 071-09541

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09541 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing west along the access road.



Inspection Photos



Photo 2. There are noxious weeds along the road that are wilted from recent weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09541 | Date: 8/4/2021

Inspection Photos



Photo 3. Facing southwest toward the well site. The location is stabilized with gravel and perennial vegetation is established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09541 | Date: 8/4/2021

Inspection Photos



Photo 4. Well sign is posted at the meter run.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09541 | Date: 8/4/2021