

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401646673

Date Received:

05/21/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

David

Phone

970-230-0435

Email

dpennington@srcenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688400169

Inspection Date: 04/27/2018

FIR Submit Date: 05/18/2018

FIR Status: _____

Inspected Operator Information:

Company Name: SRC ENERGY INC

Company Number: 10311

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 432988

Location Name: Union Number: 11-5D County: _____

Qtrqr: SWN Sec: 5 Twp: 2N Range: 68W Meridian: 6
W

Latitude: 40.170211 Longitude: -105.035003

FACILITY - API Number: 05-123- -00 Facility ID: 432988

Facility Name: Union Number: 11-5D

Qtrqr: SWN Sec: 5 Twp: 2N Range: 68W Meridian: 6
W

Latitude: 40.170211 Longitude: -105.035003

CORRECTIVE ACTIONS:

1 ☒ CA# 116406

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/29/2018

Response: CA COMPLETED

Date of Completion: 05/18/2018

Operator Comment: upon arriving the union pad, the pumper discovered an active PRV on the A-5CHZ separator. A quick exhaust wasnt operating properly. This allowed the motor valve to stay open partially. The quick exhaust was changed out and the separator was put back into production.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 116407

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/29/2018

Response: CA COMPLETED

Date of Completion: 05/18/2018

Operator
Comment: see above comments from CA 116406

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Pennington

Signed: _____

Title: Facilities superintendent

Date: 5/21/2018 6:18:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401646673	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files