

Inspection Photos
Location Name: Bailey #43-1
Location ID: 321453



Photo 1 Access road completely covered with vegetation.



Photo 2 WH Well site covered weeds.

Inspection Photos
Location Name: Bailey #43-1
Location ID: 321453



Photo 3 access road completely covered in weeds.

