



WELLHEAD ABANDONMENT FORM



<b>SITE NAME:</b> Benson Farms 12N-23HZ							<b>DATE:</b> 8/5/2021		<b>REM. PROJECT #:</b>		<b>WEATHER:</b> Sunny 80	
<b>SITE DIRECTIONS:</b> ST HWY 66 and CR 9 1/2 NORHT 0.5, EAST 0.5 SOUTH .1 INTO							<b>CLIENT:</b> Oxy					
<b>LEGALS AND LAT/LONG:</b> 40.2100493, -1049605539							<b>TASMAN PERSONNEL:</b> Brandon LeVasseur					
<b>SOIL TYPES:</b> Lean Clay - CL							<b>SURFACE GRADIENT:</b> South					
SOIL SAMPLING							FACILITY INFRASTRUCTURE					
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity			
							Above Ground Storage Tank (AST)					
8/5/2021 12:07	WH-B01 @6'	7.0	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel					
8/5/2021 12:08	WH-N01 @5'	1.8	No Staining	No Odor	Yes	N/A	Separator					
8/5/2021 12:09	WH-S01 @5'	4.4	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)					
8/5/2021 12:10	WH-E01 @5'	2.1	No Staining	No Odor	Yes	N/A	Dump Line					
8/5/2021 12:11	WH-W01 @5'	1.5	No Staining	No Odor	Yes	N/A	Wellhead		1			
8/5/2021 12:12	WHS-N01 @3"	2.6	No Staining	No Odor	Yes	N/A	Flowline					
8/5/2021 12:13	WHS-S01 @3"	2.0	No Staining	No Odor	Yes	N/A	Other:					
8/5/2021 12:14	WHS-E01 @3"	0.8	No Staining	No Odor	Yes	N/A	Soil Loads Removed					
8/5/2021 12:15	WHS-W01 @3"	0.7	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?					
8/5/2021 12:16	WH-BG01 @3'	0.6	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:					
8/5/2021 12:17	WH-BG01 @6'	1.6	No Staining	No Odor	Yes	Lab	Date		Number		CY	
8/5/2021 12:18	WH-BG02 @3'	1.6	No Staining	No Odor	Yes	Lab						
8/5/2021 12:19	WH-BG02 @6'	1.0	No Staining	No Odor	Yes	Lab						
							Total Removed		0		0	
							Disposal Facility:					
							Groundwater Recovery					
							DATE GW ENCOUNTERED:		DEPTH:			
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?					
							LNAPL OR SHEEN OBSERVED ON GW?					
GROUNDWATER SAMPLING							Date		BBLS			
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?						
							Total Removed		0			
							Disposal Facility:					

**Photographic Log**

							
<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			



**Photographic Log**

							
<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>		<b>Volume:</b>		<b>Material:</b>		<b>Volume:</b>	
<b>Contents:</b>				<b>Contents:</b>			
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			