

Inspection Photos
Location Name: Bringelson 1-32-9-58 PAD
Location ID: 424273



Photo 1 – Wells



Photo 2 – Tank Battery – SE Water Tank Label

Inspection Photos
Location Name: Bringelson 1-32-9-58 PAD
Location ID: 424273



Photo 3 – Heater Treater and Gas Meter



Photo 4 – ECD



Inspection Photos
Location Name: Bringelson 1-32-9-58 PAD
Location ID: 424273



Photo 5 – Unused Equipment removed



Photo 6 – Compressor – Wildlife Netting on Day Tanks

