

# Inspection Photos

API: 071-08278

Operator: OGRIS OPERATING LLC

Inspection Date: 8/6/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08278 | Date: 8/6/2021

## Inspection Photos



**Photo 1.** The valve box lid is open at the road intersection adjacent to the location. This needs to be closed to prevent entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08278 | Date: 8/6/2021

## Inspection Photos



**Photo 2.** There valve box is filled up with water which indicates a possible leak. There red flagging at the valve box indicating the Opertaor is aware but it is unknown if it was fixed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08278 | Date: 8/6/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08278 | Date: 8/6/2021