

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402772295

Receive Date:

08/09/2021

Report taken by:

PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Gregory Hamilton</u>	Email: <u>Gregory_Hamilton@oxy.com</u>	Mobile: <u>(970) 515-1698</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 18158 Initial Form 27 Document #: 402694136

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>310107</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>ARENDS X-62N65W 21NESE</u>		Latitude: <u>40.122146</u>	Longitude: <u>-104.661800</u>
		** correct Lat/Long if needed: Latitude: <u>40.121073</u>	Longitude: <u>-104.661659</u>
QtrQtr: <u>NESE</u>	Sec: <u>21</u>	Twp: <u>2N</u>	Range: <u>65W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SP Most Sensitive Adjacent Land Use Non-crop land

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Surface water is located approximately 1,030 feet to the west of the facility.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste

☐ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	No hydrocarbon impacts encountered	Inspection/soil samples/laboratory analytical results

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Above-ground storage tank (AST) removal activities were completed at the Arends X 21-08, 09 O SA production facility location on July 27, 2021. Groundwater was not encountered during these activities. Visual inspection and field screening of soils at two (2) former AST locations was conducted following removal activities, and soil samples were submitted for laboratory analysis to determine if a release occurred. A topographic Site Location Map showing the geographic setting of the site location is provided as Figure 1. Soil sample location and field screening data is presented in Table 1. The soil sample and field screening locations are illustrated on Figure 2.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On July 27, 2021, 2 confirmation soil samples were collected from the former AST locations, at a depth of approximately 3 inches below ground surface (bgs). The soil samples were submitted for laboratory analysis of BTEX, naphthalene, and TPH - GRO (C6-C10) by USEPA Method 8260D, TPH - DRO (C10-C28) and ORO (C28-C40) by USEPA Method 8015D. Additionally, sample AST-B02@3" was analyzed for pH, EC and SAR by saturated paste method and boron by hot water soluble soil extract method. Analytical results indicated that constituent concentrations in the 2 confirmation soil samples were in compliance with COGCC Table 915-1 standards, with exception to the pH value for sample AST-B02@3". However, based on discussions with the COGCC on August 3, 2021, the pH result was deemed acceptable as there is no indication that a release occurred at the former AST locations. Soil analytical results are presented in Tables 2 and 3.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was not encountered during AST removal activities.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

On July 27, 2021, visual inspection and field screening of soils was conducted at the former AST locations. Based on the inspection and screening results, hydrocarbon-impacted soil was not observed at the soil screening locations. Soil sample location and field screening data is presented in Table 1. Soil analytical results are presented in Tables 2 and 3. The soil sample and field screening locations are illustrated on Figure 2. The laboratory analytical report is provided as Attachment A. The field notes and a photographic log are provided as Attachment B.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 5

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 66.7

-- Highest concentration of SAR 0.239

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 0

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 915-1 0

Highest concentration of Benzene (µg/l) 0

Highest concentration of Toluene (µg/l) 0

Highest concentration of Ethylbenzene (µg/l) 0

Highest concentration of Xylene (µg/l) 0

Highest concentration of Methane (mg/l) 0

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1 0

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

On July 27, 2021, background soil samples AST-BG01@3" through AST-BG04@3" were collected from material adjacent to the former AST locations. The background soil samples were submitted for laboratory analysis of the Soil Suitability for Reclamation Parameters using standard methods appropriate for detecting the target analytes in Table 915-1. Analytical results for the background soil samples are presented in Table 3.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 0

Volume of liquid waste (barrels) 0

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Laboratory results indicate that constituent concentrations in the 2 confirmation soil samples collected from the former AST locations were in compliance with COGCC Table 915-1 allowable levels, with exception to the pH value for sample AST-B02@3". However, based on discussions with the COGCC on August 3, 2021, the pH result was deemed acceptable as there is no indication that a release occurred at the former AST locations. As a result, no soils were removed during AST removal activities. The former AST area will be contoured and re-graded to match pre-existing site conditions.

REMEDIAL ACTION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory results indicate that constituent concentrations in the 2 confirmation soil samples collected from the former AST locations were in compliance with COGCC Table 915-1 allowable levels, with exception to the pH value for sample AST-B02@3". However, based on discussions with the COGCC on August 3, 2021, the pH result was deemed acceptable as there is no indication that a release occurred at the former AST locations. Groundwater was not encountered during AST removal activities. Based on the analytical data presented herein, assessment is complete at this site and no further activities are required. As such, Kerr-McGee is requesting a No Further Action (NFA) determination for this location.

Soil Remediation Summary

<input type="checkbox"/> In Situ	<input type="checkbox"/> Ex Situ
_____ Bioremediation (or enhanced bioremediation)	_____ Excavate and offsite disposal
_____ Chemical oxidation	_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Air sparge / Soil vapor extraction	_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Natural Attenuation	_____ Excavate and onsite remediation
_____ Other _____	_____ Land Treatment
	_____ Bioremediation (or enhanced bioremediation)
	_____ Chemical oxidation
	_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☒ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other NFA Request

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

If YES:

☒ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted?

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Facility infrastructure will remain in place. The site will be reclaimed in accordance with COGCC 1000 Series Reclamation Rules following future facility decommissioning activities.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 07/27/2021

Proposed site investigation commencement. 07/27/2021

Proposed completion of site investigation. 07/27/2021

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Laboratory results indicate that constituent concentrations in the 2 confirmation soil samples collected from the former AST locations were in compliance with COGCC Table 915-1 allowable levels, with exception to the pH value for sample AST-B02@3". However, based on discussions with the COGCC on August 3, 2021, the pH result was deemed acceptable as there is no indication that a release occurred at the former AST locations. As a result, Kerr-McGee is requesting an NFA determination for this location, based on the analytical data provided herein.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Gregory Hamilton

Title: Environmental Consultant

Submit Date: 08/09/2021

Email: Gregory_Hamilton@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 08/09/2021

Remediation Project Number: 18158

Condition of Approval**COA Type****Description**

	Field observations and analytical data do not indicate a spill of hydrocarbons from the hydrocarbon storage tanks being removed. Based on the information presented, it is concluded that no further action is necessary at this time and the COGCC approves the closure request based the remediation actions taken by the Operator and the analytical results presented. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or further remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules as required by rule 913.b.(6).
1 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402772295	FORM 27-SUPPLEMENTAL-SUBMITTED
402772296	PHOTO DOCUMENTATION
402772297	SITE MAP
402772298	SOIL SAMPLE LOCATION MAP
402772299	ANALYTICAL RESULTS
402772300	OTHER
402772301	ANALYTICAL RESULTS

Total Attach: 7 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)