

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402381421

Date Received:  
04/27/2020

## FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Brian Taylor

720-587-2371

Brian.Taylor@nbenergy.com

Tesla Dougherty

970-304-5245

tesla.dougherty@nbenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696102777

Inspection Date: 04/22/2020

FIR Submit Date: 04/22/2020

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

### LOCATION - Location ID: 330166

Location Name: WARDLAW-66N64W Number: 35NENW County: \_\_\_\_\_

Qtrqtr: NENW Sec: 35 Twp: 6N Range: 64W Meridian: 6

Latitude: 40.447715 Longitude: -104.519664

### FACILITY - API Number: 05-123-00 Facility ID: 330166

Facility Name: WARDLAW-66N64W Number: 35NENW

Qtrqtr: NENW Sec: 35 Twp: 6N Range: 64W Meridian: 6

Latitude: 40.447715 Longitude: -104.519664

### CORRECTIVE ACTIONS:

1 ☒ CA# 138251

Corrective Action: Well is overdue for Mechanical Integrity Test.  
Produce well after performing successful mechanical integrity test per Rule 326 or plug well.  
To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.  
Refer to Rule 326.b.

Corrective Action Date: 07/21/2020. Extended due to COVID.

Date: 07/21/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Operator Comment: This well is part of the Alternative MIT AOC (Docket No. 180900672, Order No 1V-668) and it falls under the MIT guidance of that program. As part of the program, the well is tagged with the yellow LTSI tag to indicate that this well is part of that program.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow-up AMI Field Inspection Report Doc #696102979, dated 05/15/2020 confirms that requirement for MIT mitigated per SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed:

Title: EHS Specialist

Date: 4/27/2020 11:35:47 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402381421	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files