

TEP
GGU 13-29
Location # 323972



location



location/lack of labeling of contents in bath

TEP
GGU 13-29
Location # 323972



location



location

TEP
GGU 13-29
Location # 323972



Previous inspection photo of ditch around location



Follow up inspection photo of ditch around location



TEP
GGU 13-29
Location # 323972



Previous inspection photo of ditch around location



Follow up inspection photo of ditch around location



TEP
GGU 13-29
Location # 323972



Previous inspection photo of ditch around location



Follow up inspection photo of ditch around location



TEP
GGU 13-29
Location # 323972



Previous inspection photo of ditch around location (debris)



Follow up inspection photo of ditch around location (debris)

TEP
GGU 13-29
Location # 323972



Previous inspection photo of ditch around location



Follow up inspection photo of ditch around location



TEP
GGU 13-29
Location # 323972



Staining under tank valve

