

Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #1 well head and sign. Appears that flowline is still present on location.

Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #2 wellhead and flowlines. Water on pad and at wellhead is believed to be from recent heavy rains.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo # Pad surface and area of former Pit(s).



Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #Wellhead looking to the northeast.



Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #5 Pad area, note deadmen marker and deadmen in ground.

Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #6 Area of former Tank Battery, note Gravel present in tank battery. All gravel shall be removed prior to final Reclamation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
081-07313
REM 17616
Inspection Date: 8/4/2021
All Photos taken by Kris Neidel

Photo #7 a cut in old tank battery berm.





Inspection Photos
081-07313
REM 17616
Inspection Date: 8/4/2021
All Photos taken by Kris Neidel

Photo #8 area #1 of stained soil inside tank battery. Corrective Action: remove stained soil and sample below staining per REM # 17616



Inspection Photos

081-07313

REM 17616

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #9 area #2 of stained soil inside tank battery. Corrective Action: remove stained soil and sample below staining per REM # 17616

