

Caerus Piceance LLC
J24NW
Location # 335058



location



location

Caerus Piceance LLC
J24NW
Location # 335058



Location/lack of battery signage



location

Caerus Piceance LLC
J24NW
Location # 335058



Lack of Tank labeling



Quantity of heated separator

Caerus Piceance LLC
J24NW
Location # 335058



Lack of stabilization/compaction



Debris

Caerus Piceance LLC
J24NW
Location # 335058




Tank labeling



Tank labeling

Caerus Piceance LLC
J24NW
Location # 335058



Staining



Staining

Caerus Piceance LLC
J24NW
Location # 335058



Modified tank burner



Modified tank burner

Caerus Piceance LLC
J24NW
Location # 335058



Culverts on access road



Culverts on access road

Caerus Piceance LLC
J24NW
Location # 335058



Culverts on access road



Culverts on access road

Caerus Piceance LLC
J24NW
Location # 335058



Culverts on access road



Culverts on access road

