

Caerus Piceance LLC  
K19CNE  
Location # 335409



location



location



Caerus Piceance LLC  
K19CNE  
Location # 335409



location



location





Caerus Piceance LLC  
K19CNE  
Location # 335409



location



Lack of stabilization/compaction





Caerus Piceance LLC  
K19CNE  
Location # 335409



**Lack of stabilization/ erosion on access road**



**Lack of stabilization/ erosion on access road**





Caerus Piceance LLC  
K19CNE  
Location # 335409



Separator bath



Quantity of separator bath (Glycol)

Caerus Piceance LLC  
K19CNE  
Location # 335409



**Staining**



**Staining**





Caerus Piceance LLC  
K19CNE  
Location # 335409



**Lack of bull plug/staining**



**Lack of bull plug**

