

Inspection Photos
Location Name: Dehaan North Pad
Location ID: 460556



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Dehaan North Pad
Location ID: 460556



Photo 3: No sign displayed, unused equipment



Photo 4: No sign displayed, unused equipment

Inspection Photos
Location Name: Dehaan North Pad
Location ID: 460556



Photo 5: Unused equipment



Photo 6: Unused equipment

Inspection Photos
Location Name: Dehaan North Pad
Location ID: 460556



Photo 7: Unused equipment



Photo 8: Unused equipment

Inspection Photos
Location Name: Dehaan North Pad
Location ID: 460556



Photo 9: Unused equipment