

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW

Location ID: 334752



Photo #4737 from entrance to location.



Photo #4738 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW

Location ID: 334752



Photo #4739 No battery sign located at the tank battery.



Photo #4741 Separator bath missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW

Location ID: 334752



Photo #4740 Flow line heating insulation open ended and not capped.