



OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION FORM

C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 0775 - 6462		LEASE NAME: Green #2	
LOCATION: NENE 20 - 9N - 53		OPERATOR: Walsh	
DATE: 4-25-95 4:00 pm		INSPECTOR: Ed Binkley 8424465	
Insp. Type: CA	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input checked="" type="radio"/> Viol: Y <input checked="" type="radio"/> N <input checked="" type="radio"/> NOV: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	None	
Pits (Reserve/Production)	work pit used for cementing	
Fences	is full of oil. 4-26-95 - Dave Walsh plans to get burn permit.	
Tank Battery Equipment	gone	
Fire Walls/Berms/Dikes		
General Housekeeping	Hole appears to have been loaded with oil, tank bottoms and slop.	
Spills (Oil/Water)	Remove oil from pits immediately	
Bradenhead		
Drilling Well/Workover	Donnelly Casing Service set bottom 59x plug, stab plug @ 1000' w/ 309x.	
Surface Rehabilitation	Required 45 9x @ 30' below 940e.	
Miscellaneous	Hole should be displaced with water and mud. Appears to be oily.	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.