

# COLORADO OIL AND GAS CONSERVATION COMMISSION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100



00270106

## FIELD INSPECTION FORM

API No. 05- <i>075 - 6462</i>	LEASE NAME: <i>Green #2</i>	
LOCATION: <i>NENE20-9N-53</i>	OPERATOR: <i>Walsh</i>	
DATE: <i>4-26-96</i>	INSPECTOR: <i>EBB</i>	
Inspection Type: <i>CA</i>	Inspection Status: <i>PA</i>	PA: <i>N</i> Pass/Fail: <i>F</i>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs		
Pits (Reserve/Production)		
Fences		
Tank Battery Equipment		
Fire Walls/Berms/Dikes		
General Housekeeping		
Spills (Oil/Water)	<i>Dave Walsh is sending truck to pickup oil dumped in pit.</i>	
Bradenhead		
Drilling Well/Workover		
Surface Rehabilitation	<i>increased plug from 30 sx to 45 sx.</i>	
Miscellaneous	<i>Tag casing shoe (9 7/8 @ 402') Cement top @ 325' hard-</i>	

**CORRECTIVE ACTION REQUIRED:**

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.