

# Inspection Photos

8/10/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 479149

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 479149



**Photo 1:** Photo taken from the south end of the Location, facing northwest. Photos 1-3 provide an overview of the Location from northwest, north to northeast; topsoil salvage operations in process at time of inspection.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 479149



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 479149



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 479149



**Photo 4:** Photo shows example of stockpiled soils with a erosion log installed at base; BMPs to stabilize and protect soils currently missing.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 479149



**Photo 5:** Photo taken from the access road southwest of the Location. Photo shows the areas identified in the Location and construction drawings to be the Location entrance. Signage at the Location entrance not observed.