

# Inspection Photos

8/10/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335904

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 1:** Photos show signs installed at the Location entrance (left photo), and along the access road north of the Location (right photo).

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



August 10, 2021  
39.66066322N 108.13532388W

**Photo 2:** Photo shows well conductors remaining on the Location.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 3:** Photos shows examples of the cut slopes (left photo), and topsoil stockpiles (right photo). BMPs to protect and stabilize the cut/fill slopes of the Location, and stockpiled soils remain missing or insufficient.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 4:** Photos shows examples of the fill slopes (left photo), and topsoil stockpiles (right photo). BMPs to protect and stabilize the cut/fill slopes of the Location, and stockpiled soils remain missing or insufficient.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 5:** Photo taken from the west end of the Location. Photo shows control measures to protect/stabilize slopes remain missing or insufficient. Photo also shows example where topsoil has been utilized at the base of the fill slopes/subsoils of the Location, as a berm and sediment trap/pond to manage stormwater. Photo shows Topsoil has not been properly separated and protected, is being mixed with subsoil, and is at risk for loss due to stormwater discharge displacing the topsoil. A second trap/pond exists on the east end of the Location.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 6:** Photo of well API 05-045-14529. Gas was observed to be leaking from what appears to be the bradenhead at well API #05-045-14529. Photo also shows cellar filled with fluids



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335904



**Photo 7:** Photo on left taken from on top of the slopes above the TA wells facing west. Photo on the right taken from the southwest corner of the pad facing east towards the wells. Photo shows access to the TA wells is currently limited/restricted due to the contouring of the Location during recent pad expansion; slopes have been constructed along the eastern, southern and western perimeter of the wells; a pit has been constructed on the northern perimeter of the wells.