

Inspection Photos

8/10/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335812

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335812



Photo 1: Photo taken from the interim areas on the east end of the Location. Photo shows additional reclamation to the disturbed areas has been performed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335812



August 10, 2021
39.61629203N 108.18325589W



August 10, 2021
39.61596516N 108.18324195W

Photo 2: Photo shows unused signage at the wells has been removed, and additional BMPs to prevent wildlife access has been installed at the methanol tank.