

Inspection Photos

8/10/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335967

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335967



Photo 1: Photo patches are peeling away from the secondary containment liner.