

Inspection Photos

8/10/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 457122

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 1: Photos 1-3 used from the 4/12/2021 inspection; photos provide an aerial overview of the Location. Photos show BMPs to protect and stabilize the slopes of the Location are missing or insufficient. It was observed in this inspection that conditions remain unchanged, or have worsened since the 4/12/2021 inspection; erosion degradation evident; large cracks within the fill slope remains; BMPs to address stabilization concerns remain missing.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 4: Photo taken from the fill slopes of the Location. Photos show BMPs to protect and stabilize slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 5: Photo taken from the cut slopes of the Location. Photos show BMPs to protect and stabilize slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 6: Photo taken from the access road. Photo shows cut slopes of the access road have been regraded; areas reclaimed and hydromulch applied.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 7: Photo taken from the Location entrance. Photo shows Location signage has been installed.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 457122



Photo 8: Photo shows 4 conductors remain on the location; no drilling operations have commenced.

