

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 1 – Tank Battery



Photo 2 – NFPA Label is Fading. Recommend replacing soon



Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 3 – Tank Battery Sign



Photo 4 – Pumping Unit

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 5 – Heater Treater



Photo 6 – Gas Meter and ECD

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 7 – Risers Marked



Photo 8 – Risers Marked



Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Colorado Oil and Gas Conservation Commission
40.88876, -104.16537, 5045.5ft, 70°
08/09/2021 12:38:47

Photo 9 – Wellhead



Colorado Oil and Gas Conservation Commission
40.88834, -104.16537, 5060.5ft, 298°
08/09/2021 12:27:30

Photo 10 – Weed Overgrowth on Location

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 11 – Weed Overgrowth in Interim Reclamation Area



Photo 12 – Weed Overgrowth on Location

Inspection Photos
Location Name: Cox PC GK 26-99HZ
Location ID: 418179



Photo 13 – Weed Overgrowth on Lease Road (Looking East to County Road)