

Inspection Photos
Location Name: Hungenberg-Rasmussen-Shable Tank Battery
Location ID: 448676



Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos

Location Name: Hungenberg-Rasmussen-Shable Tank Battery

Location ID: 448676



Photo 3 – Heater Treaters




Photo 4 – Capacity Label fading